

Report ID: 18,290,051 Version: 1 14 Aug 2018 Created:

Make:	Dodge	Model:	Caliber	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,006	Registration:	LME774	Reg Expiry:	18 Jul 2018	Engine			
WoF Expiry:	20 Mar 2019	Odometer:	121,594 Kms	Good No:	18290051	Oil level	~		
VIN:	1B3H348B27D546133	Next Service:	129700	Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	pration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	sc			715		Operation	~		
PT = paint defe				$\left[\right] \left[\right]$		Noise	~		
C = crack						Clutch	-		~
P = pin dent	HID				74 <u>11</u>	CV joints	~		-
* = decals	sc 916			- Jul	HIP	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC						Performance	~		
Dealerteen		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
								mm	
						Right front	2.		mm
						Left rear	2.		mm
Condition	ac During Padulaci	action				Right rear		-	mm
Conditions During Body Inspection: Dry						Spare	2.0 mm Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-	·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Average						Head lights			
						Tail lights	~		
Carpets	Average					Indicators	~		
Demolo	Good					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RE	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Drv						Central locking	2		
Koad Con	attions During Test	Drive:	Dry			Remote locking	v v		
Engine Tir	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	-1								•
Inspected by: Dion Mair Date: 31 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: