

Report ID: 18,290,112 Version: 1 20 Sep 2018 Created:

Make:	Holden	Model:	Captiva 7	Body Style:	SUV		Pass	Fail	N/A
Year:	2016	Registration:	KFM221	Reg Expiry:	31 Jul 2018	Engine			
WoF Expiry:	2010	Odometer:	60,770 Kms	Good No:	18290112	Oil level	~		
VIN:	KL3CD2669GB528339	Next Service:	n/a	Service Histor		Smoke & fumes	~		
	RESCEZOOS GESZOSSS		11/4		103	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
		_				Performance	~ ~		
Key:	SC S	sc o				Radiator / Hoses (visual)	~		
S = scratch	Se	20		1000	X	Transmission	V		
D = dent				1 - L	BID SC	Operation			1
R = rust				10	7811X	Noise	~ ~		
PT = paint def C = crack	ect M			+		Clutch	~		
P = pin dent	Ho								~
* = decals	sc pp				ELIP ISC	CV joints Wheel bearings	~		
SC = stone chips						Wheel bearings			
W = significant scuffs									
		Nata				Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake		6.	Ļ
						Tyres (lowest observed tread depth of tyres)			
						Left front	4.5 mn		mm
						Right front	5.	8	mm
						Left rear	3.	5	mm
Conditions During Body Inspection: Dry						Right rear	3.7 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	mage & Under BOI	inet inspectic	on comments			Suspension	,		
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Daabbaa	Good					Wipers (front & rear)	~		
Dashboa	iu					Window winder FL	~		
	-					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
CD (basic test only) Number of keys									~
Road Conditions During Test Drive: Dry Central locking									
	-		-			Remote locking	~		
-	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
						_			
Inspected by: Ian Dunn Date: 20 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: