

Basic Vehicle Condition Guide


Report ID: 18,290,964

Version:

Make: Model: Landcruiser Prado **Body Style:** SUV Toyota Year: Registration: Reg Expiry: 2,002 ARZ436 18 Sep 2018 WoF Expiry: **Odometer:** 08 Dec 2018 **Good No:** 18290964 224,990 Kms VIN: JTEBN95J000095445 **Next Service: Service History:** 223,000kms

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

3 x small stone cracks in windscreen, one lower right corner & other two in middle of screen. Stone chips in windscreen. Small dent in left side running board.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Minor oil leak from around both right & left side rocker covers, which is running onto exhaust manifold & down both sides of engine.

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:**

No

Kms:

Inspected by: Jason Young

	Created: 09 Aug 2018						
1		Pass	Fail	N/A			
	Engine						
	Oil level	~					
	Smoke & fumes	~					
	Performance	\(\times \)					
	Noise	~					
	Cooling System						
	Coolant condition	~					
) }	Performance	~					
	Radiator / Hoses (visual)	~					
	Transmission						
	Operation	~					
	Noise	~					
	Clutch			~			
	CV joints	~					
	Wheel bearings	~					
	Brakes						
	Performance	~					
	Hand Brake	~					
	Tyres (lowest observed treac	l depth	of tyre	 es)			
	Left front 3.3 mm						
	Right front	3.0		mm			
	Left rear		.0	mm			
1	Right rear	4.6		mm			
_	Spare		Yes				
	Suspension						
	Suspension performance	~					
	Steering performance	\(\triangle \)					
	Shock absorbers	~					
	Air Conditioning / Heater						
_	Operation	~					
	Electrical / Accessories						
	Head lights	~					
	Tail lights	~					
	Indicators	~					
	Dashboard warning lights	~					
	Wipers (front & rear)	V V V V V V					
	Window winder FL	~					
_	Window winder FR	~					
	Window winder RL	~					
	Window winder RR	~					
	Rear view mirrors	~					
	Radio (basic test only)	~					
	CD (basic test only)	~					
	Number of keys	1					
7	Central locking	~					
_	Remote locking			~			
	Sat. Nav. (basic test only)			~			
	Reversing camera			~			
Date: 00 Arra 2010							
	Date: 08 Aug 2018						

I have read and understood this condition guide. Name: Signature: