

Report ID: 55,634 Version: 1 Created: 08 Aug 2018

Make:	BMW	Model:	X5	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,008	Registration:	HRS336	Reg Expiry:	03 Jul 2019	Engine	I		
WoF Expiry:	17 Aug 2019	Odometer:	148,890 Kms	Good No:	18290986	Oil level	~		
VIN:	WBAFE42000LK94706	Next Service:	158041	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	v		
						Performance	· ·		
Key:		-0		-161-		Radiator / Hoses (vis			
S = scratch						Transmission			
D = dent	- Glk			10		Operation	~		
R = rust				\prod	JHIA	Noise	· ·		
PT = paint def C = crack				+		Clutch			~
P = pin dent						CV joints	· ·		
* = decals	sc gig			AL.	EIIP I	Wheel bearings	V		
SC = stone chips						Brakes	V		
W = significant scuffs SC									
		Nata				Performance	<u> </u>		
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	hayed in the diagram	Hand Brake	✓	<u> </u>	
						Tyres (lowest observed tread depth of tyres)			
						Left front		4	mm
						Right front		4	mm
						Left rear		4	mm
Conditions During Body Inspection: Dry						Right rear 4 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Under Ca	irriage & Under Bor	inet inspectio	on comments			Suspension		1	
						Suspension perform	nance 🖌		
						Steering performant	ce 🖌		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning	lights 🖌		
	, Good					Wipers (front & rear)	· ·		
Dashboa	ird					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Front Seats worn & colour fading slightly						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test onl	y) 🖌		
						CD (basic test only)	· · ·		
						Number of keys	1	1	1
Road Conditions During Test Drive: Dry						Central locking	· ·		
Road Conditions During Test Drive: Dry						Remote locking			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test			~
Evidence	of Cam Belt Replac	Reversing camera			~				
	-		lot Applicable						-
Inspected by: DM Date: 25 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: