

Report ID: 18,291,009 Version: 1 30 Jul 2018 Created:

Make:	Hyundai	Model:	lx35	Body Style:	SUV		Pass	Fail	N/A	
Year:	2,015	Registration:	JCB951	Reg Expiry:	29 Jul 2018	Engine				
WoF Expiry:	30 Apr 2019	Odometer:	157,041 Kms	Good No:	18291009	Oil level	~			
VIN:	KMHJU81FMFU08986	Next Service:	159000	Service Histor	V: No	Smoke & fumes	V			
						Performance	~			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:	SPSC	-0	SC	-01-	S D SC	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust	SDCSC			215	S SC	Operation	~			
PT = paint defe		F I		$\left[\left(\right) \right]$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HIP				74 <u>11</u> 4	CV joints	~			
* = decals	SD 916			10	ELD'S	Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
	S D SC		S P SC S P SC		S D	Performance	~			
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
body inspection comments						Tyres (lowest observed tread depth of tyres)				
						Left front 4 mr			mm	
						Right front		3	mm	
						Left rear		4	mm	
Conditions During Body Inspection: Dry						Right rear	3 mm		mm	
						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
Correcto	Average					Tail lights	~			
Carpets						Indicators	~			
Panels	Average					Dashboard warning lights	~			
	Average					Wipers (front & rear)	~			
Dashboa	iu y					Window winder FL	~			
	-					Window winder FR	~			
<u>General Comments</u>						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspecter	Inspected by: Donovan Matara Date: 30 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: