

Basic Vehicle Condition Guide

Report ID: 18,291,256

Version:


Created: 24 Jul 2018

Make: Model: **Body Style:**

Year: Registration: Reg Expiry: **DER693** 15 Sep 2018 WoF Expiry: 20 Jan 2019 **Odometer: Good No:** 18291256 205,643 Kms VIN: 7A8H60J0805051722 **Next Service:** Service History: 206,250kms

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Drivers door not aligning to front panel. Stone chips in front windscreen. Plastic centre caps missing off both front wheels.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Average		
Panels	Good		
Dashboard	Good		

General Comments

Hole in rubber flooring on drivers side of cab. Reversing camera on dashboard not working.

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Kms: Yes 203,000

24 Jul 2018 Inspected by: Jason Young Date:

Name:

	Pass	Fail	N/A
Engine		•	
Oil level	~		
Smoke & fumes	v v		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	1		
Operation	~		
Noise	~		
Clutch	~		
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	 es)
Left front	1	.0	mm
Right front	3.6		mm
Left rear		.4	mm
Right rear	4.4		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	_		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	<u> </u>		V
Window winder RR			1
Rear view mirrors	~		<u> </u>
Radio (basic test only)	~		
CD (basic test only)	-		V
Number of keys	1		
Central locking	'		V
Remote locking			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Sat. Nav. (basic test only)			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Reversing camera	-		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
l	1	1	1

Signature: