

Report ID: 18,292,025 Version: 1 14 Aug 2018 Created:

Make:	Mazda	Model:	Mazda2	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,006	<b>Registration:</b>	DJY825	Reg Expiry:	05 Jul 2018	Engine	1		L
WoF Expiry:	28 Jun 2019	Odometer:	187,160 Kms	Good No:	18292025	Oil level	~		
VIN:	JM0DY10Y200208090	Next Service:	193014	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	s ssc	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	sc			715	HIV	Operation	~		
PT = paint defe		F		$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74JUL	CV joints	~		
* = decals	- Alt			Tool .	ED DSC	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan			SC			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	3.	0	mm
						Right front	3.	0	mm
						Left rear	3.	0	mm
Conditions During Body Inspection: Dry						Right rear	3.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	2		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Enging Ti	ming Machanism	<b>T</b> <sup>1</sup>				Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
	ог сапт вен керіас	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Dion Mair Date: 24 Jul 2018									
Date: 24 Jul 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....