

Report ID: 18,292,492 Version: 1 23 Jul 2018 Created:

Make:	Mazda	Model:	Bt-50	Body Style:	Utility		Pass	Fail	N/A
Year:	2,012	Registration:	GMD268	Reg Expiry:	11 Mar 2019	Engine			
WoF Expiry:	26 Sep 2018	Odometer:	158,288 Kms	Good No:	18292492	Oil level	~		
VIN:	MM0UP0YF10012616(Next Service:	160000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	SP* *	-161-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust PT = paint defect						Operation	~	v	
						Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch	V		
P = pin dent					세비	CV joints	~		
* = decals	sc 916			The	EIIP I	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	ne defects & blemishes	may not be disr		Hand Brake	~		
- · ·	pection Comments	1010.501		indy not be disp	ayea in the alagram	Tyres (lowest observed tread		oftyre))
F bumper mount broken					Left front 7 mm				
						Right front			mm
						Left rear		7	mm
						Right rear			-
Conditions During Body Inspection: Wet									mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
Dirty						Suspension performance	~		
						Steering performance			
						Shock absorbers	~		
							~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General (Comments					Window winder FR	~		
	<u>comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
Engine Ti	ming Mechanism	T:	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	огсант вен керіас	ement: N	lot Applicable	NI115;		Reversing camera			~
Inspected by: Stuart Melbourne Date: 23 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: