

Report ID: 18,292,638 Version: 1 26 Jul 2018 Created:

| Make: | Nissan | Model: | Micra | Body Style: | Sedan | | Pass | Fail | N/A |
|--|--------------------|---------------|--------------------|----------------|-------------|--|---------|--------|-----|
| Year: | 2,005 | Registration: | CNS197 | Reg Expiry: | 14 Nov 2018 | Engine | | I | 1 |
| WoF Expiry: | 31 Jul 2019 | Odometer: | 51,326 Kms | Good No: | 18292638 | Oil level | ~ | | |
| VIN: | JN1FBAK12A0722296 | Next Service: | 61000 | Service Histor | | Smoke & fumes | ~ | | |
| | 5 | | | | | Performance | ~ | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Date have not been dismantled or | | | | | | Noise | ~ | | + |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Coolant condition | ~ | | 1 |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | • | | |
| D = dent | s sc | | | The | | Operation | ~ | | |
| R = rust PT = paint def | | | | \prod | JHIH | Noise | ~ | | |
| C = crack | | | | + | | Clutch | | | ~ |
| P = pin dent | Ho | | | | | CV joints | ~ | | |
| * = decals | s sc PK | | | AL. | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | V | | |
| W = significant scuffs | | | | | | Performance | | | |
| Note: come defects & blamiches may not be disclayed in the discrement | | | | | | | | | - |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | Hand Brake | d dopth | oftime | |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | | 5 | mm |
| | | | | | | Right front | | 5 | mm |
| | | | | | | Left rear | | 3 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | : | 3 | mm |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes | | | |
| | mage & onder bor | metmspectic | <u>on comments</u> | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | - |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | 1 | |
| Interior Comments | | | | | | Operation | ~ | | |
| Good | | | | | | Electrical / Accessories | | 1 | |
| Seats | Good | | | | | Head lights | ~ | | |
| Carpets | Good | | | | | Tail lights | ~ | | |
| | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd Good | | | | | Wipers (front & rear) | ~ | | |
| | iu | | | | | Window winder FL | ~ | | |
| | - | | | | | Window winder FR | ~ | | |
| <u>General Comments</u> | | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | | | | | Remote locking | ~ | | 1 |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| ц | | | | | | _ | 1 | 1 | |
| Inspected by: Donovan Matara Date: 26 Jul 2018 | | | | | | | | | |
| I have read and understood this condition guide. Name: | | | | | | | | | |