

Report ID: 18,292,655 Version: 1 Created: 03 Aug 2018

Make:	Mazda	Model:	Axela	Body Style:	Sedan		Pass	Fail	N/A
	2,009	<b>Registration:</b>	HJN496	Reg Expiry:	30 Sep 2018	Engine	1		L
WoF Expiry:	30 Jul 2019	Odometer:	165,006 Kms	Good No:	18292655	Oil level	~		
VIN:	7AT0C13JX14101271	Next Service:	174900	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	ort is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechanio	cal inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	sc	-0	SPSC SD		P SC	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			L
D = dent R = rust	s sc			215	HILS	Operation	~		
PT = paint defect				$\left[ \left( \right) \right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HID				74116	CV joints	~		
* = decals	SDSC 916			The second		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC SC S C S C S C						Performance	~		
Body Inco	oction Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	25)
					Left front 6 mm			mm	
						Right front	e		mm
						Left rear			mm
Conditions During Body Inspection: Wet						Right rear	4 mm		
Conditions During Dody inspection. Wet						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
Air Conditio									
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboar	d					Window winder FL	~		
						Window winder FR	~		
General Co	omments					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet Central locking							~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence o	of Cam Belt Replace	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 03 Aug 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....