

Report ID: 18,292,798 Version: 1 23 Jul 2018 Created:

Make:	Holden	Model:	Captiva 5	Body Style:	SUV	٦٢		Pass	Fail	N/A	
Year:	2,011	Registration:	GAG384	Reg Expiry:	01 Nov 2018		Engine				
WoF Expiry:	26 Aug 2018	Odometer:	141,444 Kms	Good No:	18292798		Oil level	~			
VIN:	KL3DF264JBB037785	Next Service:	0	Service Histor	y: No	lŀ	Smoke & fumes	~			
						it	Performance	~			
	port is not a warranty		for and milago	Darte have not	been dismonthed or	lŀ	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends							Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition	~			
						īŀ	Performance	~			
Key:	sc	-0	S SC S SC	-161-		lŀ	Radiator / Hoses (visual)	~			
S = scratch						lŀ	Transmission	·			
							Operation	~			
R = rust PT = paint defe				\prod	JHH	lŀ	Noise	~			
C = crack							Clutch	~			
P = pin dent	Ho					lŀ	CV joints	~			
* = decals	s sc PK			- AL	EII P	۱ŀ	Wheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs						ļŀ	Performance	~			
		Note: com			laved in the diagram		Hand Brake	v v			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								-	- f h ma		
						lŀ	Tyres (lowest observed tread depth of tyres)				
						H	Left front	1.		mm	
							Right front	2		mm	
						╣┟	Left rear	4		mm	
Conditions During Body Inspection: Wet						┨┠	Right rear 5		5	mm	
						٦ŀ	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments							Suspension				
							Suspension performance	~			
							Steering performance	~			
							Shock absorbers	~			
						ļ	Air Conditioning / Heater				
						٦Ļ	Operation	~			
Interior Comments drivers seat ripped,wear and tear,							Electrical / Accessories				
Seats	unvers sea	at ripped, wear an	iu tear,				Head lights	~			
Carpets	Average						Tail lights	~			
							Indicators	~			
Panels	Average						Dashboard warning lights	~			
Derth	Average						Wipers (front & rear)	~			
Dashboa	ira j						Window winder FL	~			
						╣╏	Window winder FR	~			
General C	<u>Comments</u>						Window winder RL	~			
							Window winder RR	~			
							Rear view mirrors	~			
							Radio (basic test only)	~			
						ļľ	CD (basic test only)	~			
]	Number of keys	1		•	
Road Conditions During Test Drive: Wet						٦ŀ	Central locking	~			
						ļŀ	Remote locking	~			
Engine Timing Mechanism: Unknown							Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						╟	Reversing camera			~	
L							J				
Inspected by: Donovan Matara Date: 23 Jul 2018											

I have read and understood this condition guide.

Name:

Signature: