

Report ID: 18,292,906 Version: 1 24 Jul 2018 Created:

Make:	Ford	Model:	Laser	Body Style:	Sedan		Pass	Fail	N/A
Year:	1,994	<b>Registration:</b>	BQL595	<b>Reg Expiry:</b>	26 Aug 2018	Engine			
WoF Expiry:	05 Oct 2018	Odometer:	153,635 Kms	Good No:	18292906	Oil level	~		
VIN:	7A86G0M0703101131	Next Service:	161150	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechan	lical inspection prior to	purchase and tr	his can be arranged to	or an additional c	narge.	Coolant condition	~		
	S SC		S P SC S P SC		S P SC	Performance	~		
Key:		=		5(0)-	5130	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	SDPTC			20	HI IS	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					S PT SC	Clutch			~
P = pin dent	SDPT DE				241 <u>16</u>	CV joints	~		
* = decals		10		10	S PT SC	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
in significan	S P SC	C	S P SC S P SC		S SC	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Bonnet,roof,boot lid,front bumper needs paint ,all 4 window mouldings need paint ,						Tyres (lowest observed tread depth of tyres)			
						Left front 7			mm
						Right front	7	7	mm
						Left rear	7	7	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	hood linin	g coming off ,				Dashboard warning lights	~		
Dashboa	rd bonnet rel	ease handle brol	ase handle broken off missing ,			Wipers (front & rear)	~		
						Window winder FL	~		
	•					Window winder FR	~		
General Comments Has a slight shudder and miss ,						Window winder RL	~		
nas a slight	shuuuer ahu miss ,					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Enging Ti	ning Machanisme	<u> </u>				Remote locking			~
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 98,989						Sat. Nav. (basic test only)			~
Evidence	or Cam Beit Replac	ement: Y	es	Kms: 98	8,989	Reversing camera			~
Inspected by: Donovan Matara Date: 24 Jul 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....