

Report ID: 18,293,817 Version: 1 Created: 02 Aug 2018

Make:	Mazda	Model:	Mazda3	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2,015	Registration:	JFD335	Reg Expiry:	05 Oct 2018	Engine				
WoF Expiry:	06 Jul 2019	Odometer:	85,950 Kms	Good No:	18293817	Oil level	~			
VIN:	JM0BM543810179823	Next Service:	90000	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~			
						Performance	~			
Key: S S S S						Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission	Transmission			
D = dent R = rust SDSC SC S						Operation	~			
PT = paint defect						Noise	~			
C = crack						Clutch			~	
P = pin dent						CV joints	~			
* = decals PT SC PIP						Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
W = significant scutts SC S P P P S P						Performance	~			
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Driver door weather seal damage						Tyres (lowest observed tread depth of tyres)				
						Left front 5 mn			mm	
						Right front		5	mm	
						Left rear		1	mm	
Conditions During Body Inspection: Wet						Right rear	5 mm		mm	
						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	, Good					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
						Window winder FR	~			
General Comments						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Wet						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~			
Inspected by: Jason Law Date: 02 Aug 2018										

I have read and understood this condition guide.

Name:

Signature: