

Report ID: 18,294,038

Pass

1

V

/

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Coolant condition Performance

Radiator / Hoses (visual)

Created: 06 Aug 2018


Fail

N/A

Make: Model: Caldina **Body Style:** SUV Toyota Year: Registration: **Reg Expiry:** 2,000 **DRH583** 14 Aug 2018 **WoF Expiry: Odometer: Good No:** 06 Sep 2018 237,200 Kms 18294038 VIN: **Next Service: Service History:** 7A8H6240706048235 228434 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Left front monsoon shield broken Tailgate garnish broken

Conditions During Body Inspection: Dry

<u>Under Carriage & Under Bonnet Inspection Comments</u>

Battery flat

Interior Comments		
Seats	stains	
Carpets	Average	
Panels	Average	
Dashboard	Average	

General Comments

No radio

Knock front suspension

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

John Lindsay

Evidence of Cam Belt Replacement: Kms: 235,956 Yes

Name:

Transmission Operation V Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front 5 mm Left rear 3 mm Right rear mm 3 Spare Yes Suspension Suspension performance Steering performance / Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) / Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) ~

Reversing camera

06 Aug 2018

Signature:

1

I have read and	understood	this condition	guide.