

Report ID: 18,294,265 Version: 2 31 Jul 2018 Created:

Make:	Toyota	Model:	Caldina	Body Style:	Wagon		Pass	Fail	N/A
Year:	1,998	Registration:	GDK416	Reg Expiry:	11 Jul 2019	Engine			
WoF Expiry:	20 Dec 2018	Odometer:	340,000 Kms	Good No:	18294265	Oil level	~		
VIN:	7A8H6240706393065	Next Service:	237182	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	SD	-0			s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SSC D S SC						Operation 🖌			
PT = paint defe				$\left[\left(\right) \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				게	CV joints	~		-
* = decals	sc 916			- NL		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S P S D						Performance	~		
		Note: som	e defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Tyres (lowest observed tread depth of tyre		
Tailgate handle broken oil leak round top of motor									
						Right front			mm
						Left rear		.0	mm
						Right rear		.0	
Conditions During Body Inspection: Wet						Spare	4.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Yes			
Very dirty	/					Suspension performance	~		
						Steering performance	~		
						Shock absorbers			
							~		
						Air Conditioning / Heater			
Interior Comments						Operation			
Average						Electrical / Accessories Head lights			
Seats						-	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels						Dashboard warning lights	•		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	v		
General	Comments					Window winder FR	v		
	<u>comments</u>					Window winder RL	v		
						Window winder RR	~	-	
						Rear view mirrors		~	
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Wet							~		
Engine Ti	ming Mechanism	T:				Remote locking			~
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: Beversing camera									~
Evidence	or cam belt keplac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Stuart Melbourne Date: 24 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: