

Report ID: 18,294,310 Version: 1 25 Jul 2018 Created:

| Make: | Holden | Model: | Commodore | Body Style: | Sedan | | Pass | Fail | N/A |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------|----------------------|------------------------|--------------------|-----------------------|-----------------------------------------------------|------|------|----------|
| Year: | 2,004 | Registration: | CEE287 | Reg Expiry: | 01 Jan 2019 | Engine | | | |
| WoF Expiry: | 29 Mar 2019 | Odometer: | 133,218 Kms | Good No: | 18294310 | Oil level | ~ | | |
| VIN: | 6G1YK54F34L273538 | Next Service: | 136300 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty a quide only Conside | eration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and t | his can be arranged fo | or an additional o | charge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | -@ <u>₩</u> | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| D = dent R = rust | w dla | | | 710 | HIV | Operation | ~ | | |
| PT = paint def | ect NP | | | | 17111 | Noise | ~ | | |
| C = crack | | | | | SC SC | Clutch | | | ~ |
| P = pin dent | HIP | | | | 7414 | CV joints | | | ~ |
| * = decals | sc 916 | | | -Jos | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs W SC W | | | | | | Performance | ~ | | |
| Podylog | action Commonts | Note: son | ne defects & blemishe | s may not be disp | played in the diagram | Hand Brake | ~ | | |
| body inspection comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| Stone chips front screen | | | | | | | | mm | |
| | | | | | | Right front | | 7 | mm |
| | | | | | | Left rear | | 5 | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 6 mm | | mm |
| Conditions During Body Inspection: Wet | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | <u> </u> |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | , Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | | у | | | Remote locking | ~ | | |
| Engine Ti | ming Mechanism: | Timing (| Chain | | | Sat. Nav. (basic test only) | L. | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | | | ~ |
| | | | | | | | | | |
| Inspected by: Brian Hill Date: 25 Jul 2018 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: