

Basic Vehicle Condition Guide

Report ID: 18,294,663


Version:

Created: 15 Aug 2018

Make: Model: Honda Civic **Body Style:** Sedan Year: 2,008 Registration: Reg Expiry: **WoF Expiry: Odometer: Good No:** 20 Jul 2019 92,799 Kms 18294663 VIN: 7AT08G0WX18300296 **Next Service:** 103000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Good condition

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Clean

| <u>Interior Comments</u> | | | |
|--------------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

| | _ |
|---------|----------|
| General | Comments |

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

| | D | F-:1 | NI/A | |
|---|-----------------------|---------|----------|--|
| Funcian | Pass | Fail | N/A | |
| Engine | | | I | |
| Oil level | ~ | | | |
| Smoke & fumes | V V | | | |
| Performance | / | | | |
| Noise | / | | | |
| Cooling System | | 1 | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ✓ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | > | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | |
| Left front | 8 | 8 | mm | |
| Right front | 8 | | mm | |
| Left rear | | 8 | mm | |
| Right rear | 8 | B | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | V V V V V | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ン ン ン | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 1 | I . | I | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| | | 1 | — | |
| Sat. Nav. (basic test only) | | | 1 | |
| Sat. Nav. (basic test only) Reversing camera | | | V V | |

I have read and understood this condition guide.

Stuart Melbourne

Name:

Signature:

Date: 15 Aug 2018