

Report ID: 18,294,732 Version: 1 Created: 27 Jul 2018

| Make: | Toyota | Model: | Blade | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|------------------------|---------------|------------------------|-----------------|---------------------------------------|--|------|------|----------|
| Year: | 2,008 | Registration: | | Reg Expiry: | | Engine | I | L | L |
| WoF Expiry: | 20 Jul 2019 | Odometer: | 110,845 Kms | Good No: | 18294732 | Oil level | ~ | | |
| VIN: | 7AT0H656X18026785 | Next Service: | 121,000kms | Service Histor | | Smoke & fumes | ~ | | |
| | | | 121)00011115 | | | Performance | ~ | | |
| | port is not a warranty | | с I I | | | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | STO | A CO | | 10c | X | Transmission | v | | |
| D = dent | - Alle | | | 1 - L | | Operation | ~ | | |
| R = rust | | | | 10 | JHIH | Noise | ~ | | |
| PT = paint defe C = crack | ect M | | | + | | Clutch | ~ | | ~ |
| P = pin dent | Ho | KI | | | JUII — | CV joints | ~ | | |
| * = decals | MIR | | | AL- | | Wheel bearings | | | |
| SC = stone chi | ps U | VA | | (a) | | | ~ | | |
| W = significant scuffs | | | | | | Brakes | | | |
| | | N | | | | Performance | ~ | | |
| Body Insp | pection Comments | Note: son | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | | | Ļ |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 7 | 7 | mm |
| | | | | | | Right front | nt 7 | | mm |
| | | | | | | Left rear | 7 mm | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 7 mm | | |
| | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| Tidy . | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | , Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | |
| | • | | | | · · · · · · · · · · · · · · · · · · · | Window winder FR | ~ | | <u> </u> |
| General Comments | | | | | | Window winder RL | ~ | | |
| Nice tidy hatch . | | | | | | Window winder RR | ~ | | <u> </u> |
| | | | | | | Rear view mirrors | ~ | | 1 |
| | | | | | | Radio (basic test only) | ~ | | <u> </u> |
| | | | | | | CD (basic test only) | ~ | | <u> </u> |
| | | | | | | Number of keys | 1 | | 1 |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| Road Conditions During Test Drive: Dry | | | | | | Remote locking | ~ | | <u> </u> |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | - | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | | | ~ |
| | • | • | | | | | | | |
| Inspected by: Daryll Timms Date: 27 Jul 2018 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: