

Report ID: 18,294,824

Pass

1

~

/

V

1

Tyres (lowest observed tread depth of tyres)

Version: 2

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Right front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 09 Aug 2018

Fail

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

7

7

7

1

/

/

2


~

Yes

Make: Model: Hilux **Body Style:** Utility Toyota Year: Registration: **Reg Expiry:** 2,008 FKG248 01 Jan 2019 WoF Expiry: **Odometer:** 04 Feb 2019 **Good No:** 217,790 Kms 18294824 VIN: MR0FZ29GX01722647 **Next Service: Service History:** 222500 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments						
Seats	Average					
Carpets	Hole in drivers mat					
Panels	Scratches on panels					
Dashboard	Scratches on dashboard					

## **General Comments**

Inspected by:

**Road Conditions During Test Drive:** Dry

**Engine Timing Mechanism:** Cambelt

John Lindsay

**Evidence of Cam Belt Replacement:** Yes Kms: 196,220

Name: .....

Date: 09 Aug 2018

	3
Signature:	

	l have reac	land	und	lerstaad	l thic	condition	aniide
ľ	i ilave reac	una	ario	10131000		condition	gaiac