

Basic Vehicle Condition Guide

Report ID: 18,294,914

Pass

1

V

V

V

1

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Operation

Noise

Clutch

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Suspension performance

Steering performance

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL

Window winder RR

Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Shock absorbers Air Conditioning / Heater

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

Created: 08 Aug 2018

Fail

N/A

1

mm

mm

mm

 mm

7

5

5

1

1

/

2

~


~

Yes

Make: Audi Model: RS6 **Body Style:** Sedan Year: Registration: **Reg Expiry:** 2,004 LBC556 **WoF Expiry: Odometer: Good No:** 17 Aug 2016 88,707 Miles 18294914 VIN: **Next Service: Service History:** WUAZZZ4B44N90138 90000

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

Dry

General Comments

Dash cup holder broken. Drivers sunvisor light not working. Screen, Radio, CD, NAV systems unable to make to work. Bonnet strut soft. Trans fluid leak. Inner roof mirror tint changed. Dash low tyre pressure light on.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** Kms: No

I have read and understood this condition guide.

Inspected by: **Eddie Marsters** Date: 08 Aug 2018

Name:	Signature: