

Report ID: 18,295,028


Version: 1

Created: 25 Jul 2018

Make:	Mazda	Model:	Bounty	Body Style:	Utility
Year:	2,006	Registration:	DBT356	Reg Expiry:	21 Jun 2019
WoF Expiry:	26 Jul 2019	Odometer:	362,346 Kms	Good No:	18295028
VIN:	MM0UNY0W2004105	Next Service:	377310	Service Histor	y: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stonechips on windscreen. Paint coming off LHS of tray. Hole on RF corner of roof under tape. No towbar tongue. Dents in LH sill.

Screw holes and marks on dash. Wear on RF seat. Ignition key not working in RF door lock.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Rust in radiator support panel where it joins to RF inner guard. Rust in bottom edge of radiator support panel. Engine has oil seepage Cambelt has been changed but cannot read kms, so should be checked.

<u>Interior Comments</u>					
Seats	Average				
Carpets	Average				
Panels	Average				
Dashboard	Average				

General Comments

Slight whine in diff.

Drives ok.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Kms: Yes 1

Inspected by: Roger King 25 Jul 2018

Name:

	Pass	Fail	N/A					
Engine								
Oil level	~							
Smoke & fumes	~							
Performance	~							
Noise	~							
Cooling System								
Coolant condition	~							
Performance	ı							
Radiator / Hoses (visual)	ν ν							
Transmission	_							
Operation	~							
Noise	~							
Clutch	<i>'</i>							
CV joints			~					
Wheel bearings	1		<u> </u>					
Brakes								
Performance	V							
Hand Brake	•							
Tyres (lowest observed tread	l denth	of tyre) 					
Left front		-	mm					
Right front		3	mm					
Left rear	3		mm					
Right rear	2							
	-	2	mm					
Spare Suspension		Yes						
-								
Suspension performance Steering performance	~							
Shock absorbers	-							
	<i>V</i>							
Air Conditioning / Heater	_							
Operation	•							
Electrical / Accessories			1					
Head lights	<i>\</i>							
Tail lights	~							
Indicators	~							
Dashboard warning lights	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \							
Wipers (front & rear)	-							
Window winder FL	~							
Window winder FR	~							
Window winder RL			~					
Window winder RR			~					
Rear view mirrors	~							
Radio (basic test only)	~							
CD (basic test only)	~							
Number of keys	1	ı						
Central locking	~							
Remote locking			~					
Sat. Nav. (basic test only)			~					
Reversing camera			~					
Date: 25 Jul 201								

Signature: