

Report ID: 18,296,439 Version: 3 Created: 24 Aug 2018

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2,008	<b>Registration:</b>	ENA289	<b>Reg Expiry:</b>	10 Jun 2018	Engine			
WoF Expiry:	14 Nov 2018	Odometer:	174,797 Kms	Good No:	18296439	Oil level	~		
VIN:	VSKCVND40A0299354	Next Service:	180,190kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	D					Performance	~		
Key:		-0	ls	500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust	S PT SC W			710		Operation	~		
PT = paint defe	ect NP				101/1	Noise	~		
C = crack					S SC	Clutch			~
P = pin dent	HIP				74116	CV joints	~		
* = decals	sc 916	10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scurs S S S S S D S DPT SC						Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	mm		
						Right front	7	.0	mm
						Left rear	3	.0	mm
Conditions During Body Inspection: Wet						Right rear	2	.5	mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Underbody	Surface Rust					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Comoto	Carpets m	issing				Tail lights	~		
Carpets		-				Indicators	~		
Panels	Poor					Dashboard warning lights	~		
Deckler	rd Average					Wipers (front & rear)	~		
Dashboa	iu j					Window winder FL	~		
	-					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Ca Thach Date: 24 Aug 2018									
Date: 24 Aug 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....