

Report ID: 18,297,684 Version: 1 Created: 01 Aug 2018

Make:	Hyundai	Model:	Getz	Body Style:	Hatchback	]	Pass	Fail	N/A	
Year:	2,005	<b>Registration:</b>	CSZ937	<b>Reg Expiry:</b>	01 Oct 2018	Engine	1	1	1	
WoF Expiry:	02 Jul 2019	Odometer:	83,358 Kms	Good No:	18297684	Oil level	~			
VIN:	KMHBU51AR5U40599	Next Service:	90000	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechar	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:		-0		-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
D = dent $R = rust$ SC $R = rust$						Operation	~			
PT = paint defect						Noise	~			
C = crack						Clutch	~			
P = pin dent						CV joints	~			
* = decals SC 919						Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs						Performance	~			
Podylog	action Commonts	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments Right roar two on woar indicator						Tyres (lowest observed tread depth of tyres)				
Right rear tyre on wear indicators						Left front 4.0 mm				
						Right front		.0	mm	
						Left rear		.0	mm	
Conditions During Body Inspection: Dry						Right rear		.0	mm	
						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
	Average					Tail lights	~			
Carpets						Indicators	~			
Panels	Average					Dashboard warning lights	~			
	Average					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
						Window winder FR	~			
General Comments						Window winder RL	~			
Battery requires replaement						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~	
							1.0		-	
Inspected by: Greg Morgan Date: 27 Jul 2018										

I have read and understood this condition guide.

Name: .....

Signature: .....