

Report ID: 18,297,991 Version: 1 26 Jul 2018 Created:

Make:	Mazda	Model:	Familia	Body Style:	Sedan		Pass	Fail	N/A
Year:	1,997	Registration:	AUA939	Reg Expiry:	11 Aug 2018	Engine	I	I	1
WoF Expiry:	11 Nov 2018	Odometer:	167,005 Kms	Good No:	18297991	Oil level	~		
VIN:	7A8C10H0702308043	Next Service:	154885	Service Histor	y: No	Smoke & fumes		~	
						Performance	~	-	
	port is not a warranty	avation is made	for one and miles as	Danta hava nat	haan diamantlad ar	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	SC SC	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		
D = dent				The	EID PT W	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint defe C = crack				+	SC	Clutch	•		~
P = pin dent	Ho				JUII —	CV joints		~	
* = decals	sc pp			AL-	ENR			V	
SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
		N				Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~	<u> </u>	Ļ
No wheel trims. Left rear step plate missing cig burn holes in drivers seat. Right side boot lid light. Left						Tyres (lowest observed tread depth of tyres)			
parklight not working. Central locking not working left rear door						Left front	4 mm		
						Right front	· ·	4	mm
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear		7 mm	
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
CV boots sp	lit and joints are noisy.	Engine oil leak				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights	~		
Comoto	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
	<u>Comments</u>					Window winder RL	~		
Some exha	ust smoke and fumes					Window winder RR	~		-
						Rear view mirrors	~		1
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		1
Road Con	ditions During Test	t Drive:	Dry			Central locking	-	~	
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
	-								
Inspected by: Brian Hill Date: 26 Jul 2018									
I have read and understood this condition guide. Name:									