

Basic Vehicle Condition Guide

Report ID: 18,298,279


Version:

Created: 01 Aug 2018

Make: Model: Caldina **Body Style:** Wagon Toyota Year: 1,999 Registration: CAF963 Reg Expiry: 07 May 2019 WoF Expiry: **Odometer: Good No:** 18298279 11 Jan 2019 269,783 Kms VIN: 7A8H6240704034582 **Next Service: Service History:** 279,000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



LH wing mirror not working sideways

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil leak from engine and gearbox

Interior Comments			
Seats	Good		
Carpets	Average		
Panels	Average		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Kms: No

Inspected by: Mathew Varghese Date: 31 Jul 2018

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	\(\times \)			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch	\(\times \)			
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	6	.0	mm	
Right front	6	.0	mm	
Left rear			mm	
Right rear			mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	\(\times \) \(\t			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)		~		
CD (basic test only)		~		
Number of keys	1	l .	-	
Central locking	~			
Remote locking			~	
Sat. Nav. (basic test only)			~	
Reversing camera			~	

I have read and understood this condition guide.

Name:

Signature: