

Report ID: 18,298,320 Version: 3 Created: 23 Aug 2018

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,006	Registration:	HFN521	Reg Expiry:	19 Jul 2019	Engine			L
WoF Expiry:	06 Apr 2019	Odometer:	126,250 Kms	Good No:	18298320	Oil level	~		
VIN:	7AT0C13JX14302308	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SD W	-0	S SPT	$- \square$	<u>S PT</u>	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	s sc			The	HILS	Operation	~		
PT = paint defe				$\left[\right] \left[\right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIC				게止	CV joints	~		
* = decals	sc 916			The	ELL'S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W S S S W S						Performance	~		
D. L.L.		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	V		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			<u> </u>
						Left front			mm
						Right front	-		mm
						Left rear			mm
Conditions During Rody Inspections						Right rear	3 mm 3 mm		-
Conditions During Body Inspection: Wet						Spare			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	-	•				Suspension performance	~		
						Steering performance	• •		
						Shock absorbers	• •		
	Air Conditioning / Heater	v							
						Operation	~		
Interior Comments						Electrical / Accessories			
Good						Head lights	~		
Seats						Tail lights	v v		
Carpets	Good					Indicators			
	Good						~		
Panels						Dashboard warning lights	V		
Dashboa	rd Good					Wipers (front & rear) Window winder FL	v		
							V		-
General (Comments					Window winder FR	~		
	<u>comments</u>					Window winder RL	~		
						Window winder RR	~		-
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain						Remote locking	~		
						Sat. Nav. (basic test only)			~
		Cillent. N	lot Applicable	11115.		Reversing camera			~
Inspected by: Xinghui Lin Date: 23 Aug 2018									

I have read and understood this condition guide.

Name: