

Report ID: 18,298,365 Version: 1 Created: 01 Aug 2018

Signature:

Make:	Subaru	Model:	Impreza	Body Style: Hatchback		Pass	Fail	N/A
Year:	2,008	Registration:		Reg Expiry:	Engine			
WoF Expiry:	24 Jul 2019	Odometer:	114,275 Kms	Good No: 18298365	Oil level	~		
VIN:	7AT0GF09X18006142	Next Service:	124,271kms	Service History: No	Smoke & fumes	~		
	////00/05///0000/12			, 110	Performance	~		
	port is not a warranty				Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends					Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Coolant condition			
					Performance	~		
Key:		-0			Radiator / Hoses (visual)	~		
S = scratch						Transmission		
D = dent	- Alle				Operation	~		
R = rust					Noise	~		
PT = paint def C = crack	ect M				Clutch			~
P = pin dent	Ho					~		V
* = decals	MIR				CV joints Wheel bearings	-		
SC = stone chips								L
W = significant scuffs					Brakes			
		Nata			Performance	~		
Body Ins	pection Comments	Note: som	he defects & biemisnes	may not be displayed in the diagram	Hand Brake			
					Tyres (lowest observed tread depth of tyres)			
					Left front	6)	mm
					Right front	6	ò	mm
					Left rear	6	6	mm
Conditions During Body Inspection: Dry					Right rear	6	6 mm	
					Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension			
Tidy .					Suspension performance	~		
					Steering performance	~		
		Shock absorbers	~					
					Air Conditioning / Heater			
					Operation 🖌			
Interior Comments					Electrical / Accessories			
Seats	Good				Head lights	~		
	Good				Tail lights	~		
Carpets					Indicators	~		
Panels	Good				Dashboard warning lights	~		
	, Good				Wipers (front & rear)	~		
Dashboa	rd				Window winder FL	~		
	•				Window winder FR	~		
General Comments					Window winder RL	~		
Good looki	ng, tidy hatch .				Window winder RR	~		
					Rear view mirrors	~		
					Radio (basic test only)	~		
					CD (basic test only)	~		
					Number of keys	1		L
Road Conditions During Test Drive: Drv					Central locking	· ·		
Rodu Con	uning les	l Drive:	Dry		Remote locking	~		
Engine Ti	ming Mechanism:	Cambelt	t		Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 93,167					Reversing camera			~
		1						~
Inspected by: Daryll Timms Date: 01 Aug 2018								

I have read and understood this condition guide.

Name: