

Report ID: 18,298,639 Version: 1 23 Aug 2018 Created:

Make:	Honda	Model:	AIR	Body Style: SUV]	Pass	Fail	N/A
Year:	2,005	Registration:		Reg Expiry:	Engine			
WoF Expiry:	24 Jul 2019	Odometer:	68,476 Kms	Good No: 18298639	Oil level	~		
VIN:	7AT08GBNX18003584	Next Service:	78472	Service History: No	Smoke & fumes	~		
					Performance	~		
	port is not a warranty	vation is made	for and milaana	Parts have not been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends					Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Coolant condition	~		
					Performance	~		
Key:		-0			Radiator / Hoses (visual)	~		
S = scratch					Transmission			
D = dent					Operation 🖌			
R = rust PT = paint def					Noise	~		
C = crack					Clutch	•		~
P = pin dent					CV joints	~		•
* = decals	616				Wheel bearings	~		
SC = stone chips					Brakes			
W = significant scuffs					Performance	~		
		Note: som		may not be displayed in the diagram	Hand Brake	~		
Body Insp	pection Comments	Note: Joh				•	oftyre))
					Tyres (lowest observed tread depth of tyres) Left front 7 mm			
						7		mm
					Right front	7		mm
					Left rear	6		mm
Conditions During Body Inspection: Dry					Right rear	7		mm
Under Carriage & Under Bonnet Inspection Comments					Spare Yes			
		<u>ince inspectie</u>	<u>in comments</u>		Suspension			
					Suspension performance	~		
					Steering performance	~		
					Shock absorbers	~		
					Air Conditioning / Heater	1		
Interior Comments					Operation 🖌			
Good					Electrical / Accessories			
Seats	0000				Head lights	~		
Carpets	Good				Tail lights	~		
	Cood				Indicators	~		
Panels	Good				Dashboard warning lights	~		
Dashboa	Good				Wipers (front & rear)	~		
					Window winder FL	~		
					Window winder FR	~		
General C	<u>Comments</u>				Window winder RL	~		
					Window winder RR	~		
					Rear view mirrors	~		
					Radio (basic test only)	~		
					CD (basic test only)	~		
					Number of keys	1		
Road Conditions During Test Drive: Dry						~		
	-		-		Remote locking			~
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)								~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:	Reversing camera			~
Inspected by: John Lindsay Date: 23 Aug 2018								

Name:

Signature: