

Basic Vehicle Condition Guide

Reg Expiry:

Report ID: 18,298,747

Version: 1

Created: 22 Aug 2018

 Make:
 Honda
 Model:
 FIT
 Body Style:
 Hatchback

 WoF Expiry:
 24 Jul 2019
 Odometer:
 96,348 Kms
 Good No:
 18298747

 VIN:
 7AT08G2YX18230585
 Next Service:
 106327
 Service History:
 No


Registration:

Note: This report is not a warranty

2,009

Year:

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Greg Morgan Date: 21 Aug 2018

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	\(\times \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	6	.0	mm	
Right front	6	.0	mm	
Left rear	6.0		mm	
Right rear	6.0		mm	
Spare		N/A		
Suspension				
Suspension performance	~			
Steering performance	V			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	V V V V			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)			~	
CD (basic test only)			~	
Number of keys	1			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera			'	

Signature: