

Report ID: 18,298,832 Version: 1 Created: 06 Sep 2018

Make:	Toyota	Model:	Ractis	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,009	Registration:		Reg Expiry:		Engine	1		L
WoF Expiry:	,	Odometer:	63,252 Kms	Good No:	18298832	Oil level	~		
VIN:	7AT0H652X18140100	Next Service:		Service Histor		Smoke & fumes	~		<u> </u>
						Performance	~		<u> </u>
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	¥		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	s di			The		Operation	~		
PT = paint defe				$\left[\right] \left[\right]$		Noise	~		
C = crack					D	Clutch			~
P = pin dent	HID				7414	CV joints	~		
* = decals	- 91E			The		Wheel bearings	~		
SC = stone chips						Brakes			L
W = significant	t scuffs W					Performance	~		
Podula	noction Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			L 2S)
						Left front	. 7		mm
						Right front	7		mm
						Left rear	7		mm
Conditions During Body Inspection: Dry						Right rear	7 mm		mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	screw hole	es both front doo	or trims			Dashboard warning lights	~		
	Card					Wipers (front & rear)	~		<u> </u>
Dashboa	rd Good					Window winder FL	~		<u> </u>
	1					Window winder FR	~		<u> </u>
General Comments						Window winder RL	~		<u> </u>
						Window winder RR	~		
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	2		L
Road Conditions During Test Drive: Dry							~		
Remote locking							~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera									~
Inspected by: John Lindsay Date: 06 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: