

| | | | Air Conditioning / Heater | | |
|---|---|---|-----------------------------|---|---|
| | | | Operation | ~ | |
| Interior Comments | | [| Electrical / Accessories | | |
| Seats | Good | | Head lights | ~ | |
| Carpets | Good | | Tail lights | ~ | |
| | | | Indicators | ~ | |
| Panels | Good | | Dashboard warning lights | ~ | |
| Dashboard | Good | | Wipers (front & rear) | ~ | |
| | | | Window winder FL | ~ | |
| | | | Window winder FR | ~ | |
| General Comments Gear shift button cover missing | | | Window winder RL | ~ | |
| | | | Window winder RR | ~ | |
| | | | Rear view mirrors | ~ | |
| | | | Radio (basic test only) | ~ | |
| | | | CD (basic test only) | ~ | |
| | | | Number of keys | 2 | |
| Road Conditions During Test Drive: Wet | | | Central locking | ~ | |
| | | [| Remote locking | ~ | |
| Engine Timing Mechanism: Timing Chain | | | Sat. Nav. (basic test only) | | ~ |
| Evidence of Car | n Belt Replacement: Not Applicable Kms: | | Reversing camera | > | |
| Inspected by: Xinghui Lin | | | Date: 09 Aug 2018 | | |

I have read and understood this condition guide.

Name:

Signature:

1

09 Aug 2018

Fail

N/A

V

mm

mm

mm

mm

3

3

2.5

2.5

Yes