

Report ID: 18,299,816

Pass

~

~

/

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

**Transmission** 

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 02 Aug 2018

Fail

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

3

2

5

1

/

/

~

2


1

Yes

Make: Model: ΚIΑ RIO **Body Style:** Hatchback Year: 2,007 Registration: EAR553 **Reg Expiry:** 25 Jul 2018 WoF Expiry: **Odometer: Good No:** 18299816 20 Jun 2019 124,696 Kms VIN: **Next Service: Service History:** KNADE243376273643 134300 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Dent in LH sill. Rear bumper not fitting correctly LHS. Stonechips on windscreen. Cannot load CD into player. Parcel tray mounts broken.

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Average condition.

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

## **General Comments**

Drives ok.

**Road Conditions During Test Drive:** Dry

	Remote locking	V			
	Sat. Nav. (basic test only)		~		
Kms:	Reversing camera		~		
Date: 02 Aug 2018					
Name: Signature:					

Engine Timing Mechanism: Cambelt	Sat. Nav. (basic test only)	
Evidence of Cam Belt Replacement: No	Kms:	Reversing camera 🗸
Inspected by: Roger King		Date: 02 Aug 2018
have read and understood this condition guide.	Name:	Signature: