

Basic Vehicle Condition Guide

Report ID: 18,300,982

Version:

Engine

Oil level

Smoke & fumes

Created: 27 Jul 2018

Pass

1


N/A

Fail

Make: Holden Model: **Body Style:** Hatchback Astra Year: Registration: **Reg Expiry:** 2,005 CYD943 25 Jul 2019 WoF Expiry: **Odometer: Good No:** 18300982 05 Jun 2019 147,890 Kms VIN: **Next Service: Service History:** W0L0AHL4855228522 137200 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Moisture in the RR tail light,

Conditions During Body Inspection: Dry

<u>Under Carriage & Under Bonnet Inspection Comments</u>

<u>Interior Comments</u>		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Average	

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement:

Donovan Matara

Kms: Yes

Name:

117,963

Performance V Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front mm 6 Left rear 3 mm Right rear mm 4 Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera 1

27 Jul 2018

Signature:

Date:

I have read and	understood this	condition guide.