

Report ID: 18,301,036 Version: 1 14 Aug 2018 Created:

Make:CadillacModel:CTSBody Style:SedanPaYear:2,010Registration:FFU455Reg Expiry:24 Aug 2018EngineWoF Expiry:08 Aug 2019Odometer:111,182 KmsGood No:18301036Oil levelVIN:1G6DR57T790106563Next Service:121000Service History:NoSmoke & fumes	s Fail	N/A
WoF Expiry: 08 Aug 2019 Odometer: 111,182 Kms Good No: 18301036 Oil level		
Performance		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Darts have not been dismantled or Noise		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.		1
Key: S SC S P SC S P SC S D SC Radiator / Hoses (visual) V		
S = scratch		
D=dent SSC 6/6 Operation		
R = rust Operation V PT = paint defect Noise V		
C = crack		~
P = pin dent CV joints		-
* = decals SC 999 Wheel bearings		
SC = stone chips		<u> </u>
W = significant scuffs SC S S S S S S S S S Performance		
Note: come defecte 8 blemiches: may not be displayed in the dispram		+
Body Inspection Comments Note: some defects & blemisnes may not be displayed in the diagram Hand Brake / Tyres (lowest observed tread de	th of tw	
Left front		
Right front	4	mm
Left rear	5	mm
	5	mm
Conditions During Body Inspection: Wet Right rear	6	mm
Under Carriage & Under Bonnet Inspection Comments Suspension	Yes	
Suspension performance		
Steering performance		
Shock absorbers		
Air Conditioning / Heater		
Interior Comments		
Seats read lights read lights		
Carpets Average Tail lights		
Average Indicators		
Panels Dashboard warning lights V	_	
Dashboard Average Wipers (front & rear)	_	
Window winder FL	_	
General Comments Window winder FR Window winder RI		
	_	
Window winder RR	_	
Rear view mirrors	_	<u> </u>
Radio (basic test only)		
CD (basic test only)		
Number of keys 2		
Road Conditions During Test Drive: Wet Central locking	_	<u> </u>
Engine Timing Mechanism: Unknown Sat Nav (basic test only)	_	<u> </u>
Suidence of Com Bolt Bankscoments and the Kings	~	<u> </u>
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera		~
Inspected by: Donovan Matara Date: 14 Aug 2018		

I have read and understood this condition guide.

Name:

Signature: