

Report ID: 18,301,164 Version: 3 Created: 28 Sep 2018

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2013	<b>Registration:</b>	GWG889	<b>Reg Expiry:</b>	16 Feb 2019	Engine	1		
WoF Expiry:	21 May 2019	Odometer:	200,363 Kms	Good No:	18301164	Oil level	~		
VIN:	MR0FZ22G601192025	Next Service:	200055	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission	<u>, , , , , , , , , , , , , , , , , , , </u>		
D = dent R = rust PT = paint defect C = crack						Operation	~		
						Noise	~		
						Clutch	· ·		
P = pin dent						CV joints	~		
*=decals SC 919						Wheel bearings	~		
SC = stone chips						Brakes	V		<u> </u>
W = significant scuffs						Performance V			
Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments							•	ofture	
Front bumper flares missing						Left front	Tyres (lowest observed tread depth of tyres		
								7 mm	
						Right front		7	mm
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	metinspectic	<u>on comments</u>			Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Deckle	Average					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Clutch operation ok at time of report but clutch is at end of travel						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
			- ' J			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	'es	Kms: 15	0,815	Reversing camera			~
ц		-	1	í					
Inspected by: Ca Thach Date: 28 Sep 2018									
I have read and understood this condition guide. Name:									