

Report ID: 18,301,366 Version: 2 Created: 13 Aug 2018

Make:	Holden	Model:	Commodore	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,007	Registration:	DZM378	Reg Expiry:	01 Mar 2019	Engine	I		L
WoF Expiry:	,	Odometer:	209,827 Kms	Good No:	18301366	Oil level	~		
VIN:	6G1EK55B78L939269	Next Service:	not known	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
	SC		D SC PT SC		SC W	Performance	~		
Key:	ISC IC	-0	D SC PT SC		I SC W	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust						Operation	V		
PT = paint defe	ect NP				10111	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HP				24114	CV joints			~
* = decals	sc Ale	10		10	ELC'S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W – significan	SC W		SC			Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Battery cover missing						Tyres (lowest observed tread depth of tyres)			
						Left front	3.0 mm		mm
						Right front	4.	0	mm
						Left rear	3.	0	mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Comoto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Daabbaa	Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
	-					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry							~		
Г.,			-			Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Brian Hill Date: 27 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: