

Report ID: 18,301,384 Version: 2 Created: 14 Aug 2018

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2,009	Registration:	EWG586	Reg Expiry:	25 Jul 2019	Engine			
WoF Expiry:	22 Dec 2018	Odometer:	182,156 Kms	Good No:	18301384	Oil level	~		
VIN:	MNTCPUD22A000001	Next Service:	192000	Service Histor	y: No	Smoke & fumes	r		
						Performance	r		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	sc sc	-01-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	SC DI			715	HIV	Operation	~		
PT = paint defe		F		$\left[\left(\right) \right]$		Noise	~		
C = crack					D SC	Clutch	~		
P = pin dent	HIP				74114	CV joints	~		
* = decals	sc 916			The second		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC SC SC						Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	r		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front 7.0			mm
						Right front	7	.0	mm
						Left rear	7	.0	mm
Conditions During Body Inspection: Wet						Right rear			mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Usual turbo	whine					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
r						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Poor					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
			U I Y			Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
								í	
Inspected by: Brian Hill Date: 30 Jul 2018									

I have read and understood this condition guide.

Name: