

Report ID: 18,301,912 Version: 1 Created: 30 Jul 2018

Make:	Chrysler	Model:	PT Cruiser	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,004	Registration:	FTP712	Reg Expiry:	29 May 2018	Engine			
WoF Expiry:	2,004 20 Apr 2019	Odometer:	119,356 Kms	Good No:	18301912	Oil level	~		
VIN:	1C8F4B8964T253128	Next Service:	119,990 Kins	Service Histor		Smoke & fumes	~		
						Performance	~		+1
	port is not a warranty		<b>C</b> 1 1			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		++
Key:		-0	ls		s	Radiator / Hoses (visual)	~		++
S = scratch						Transmission			
D = dent	sc dl			1 - L	BIDS	Operation	~		
R = rust				10	7HH	Noise	~		
PT = paint defe C = crack	ect M			+	SC	Clutch	V		
P = pin dent	H	KI			JUII ——				~
* = decals	s sc pp			SI	ANA	CV joints	~		
SC = stone chips						Wheel bearings			
W = significant scuffs S S S									
		N				Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake		<u> </u>	Ļ
Moisture inside both tail lamps					Tyres (lowest observed tread depth of tyres)				
Tail gate gas strut weak RR power window not working						Left front	6	5	mm
Audio not v	vorking, knobs missing					Right front	6	5	mm
						Left rear		3	mm
Conditions During Body Inspection: Dry						Right rear	3	3	mm
Under Carriage & Under Pennet Inspection Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension	1	-	
Engine oil le Transmissio						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation		~	
						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashhaa	Average					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
	<u>Comments</u>					Window winder RL	~		
Steering knocking noise RH wing mirror vibration						Window winder RR		~	
Rattling from interior						Rear view mirrors		~	
Engine vibration, RPM fluctuation in idle AC not working						Radio (basic test only)		~	
AC NOT WOR	king					CD (basic test only)		~	
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	-		UT y			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)		-	~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 10	07,076	Reversing camera			~
							1		
Inspected by: Mathew Varghese Date: 30 Jul 2018									
I have read and understood this condition guide. Name:									