

Report ID: 56,054 Version: 1 20 Aug 2018 Created:

| Make: | Audi | Model: | A4 | Body Style: | Wagon | | Pass | Fail | N/A |
|--|--------------------------|----------------------|------------------------|--------------------|--------------|--|------|------|-----|
| Year: | 2,007 | Registration: | JTT431 | Reg Expiry: | 07 Dec 2018 | Engine | | 1 | |
| WoF Expiry: | 14 Aug 2019 | Odometer: | 109,260 Kms | Good No: | 18302121 | Oil level | ~ | | |
| VIN: | WAUZZZ8E07A23341. | Next Service: | Just Serviced | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | Noise | ~ | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and tl | his can be arranged fo | r an additional c | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | sc | -0 | | -161- | w | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| | | | | | | Operation | ~ | | |
| R = rust PT = paint defect | | | | | | Noise | ~ | | |
| C = crack | | | | | | Clutch | • | | ~ |
| P = pin dent | | | | | | CV joints | ~ | | |
| *= decals | | | | | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | V | | |
| W = significant scuffs SC W | | | | | | Performance | | | |
| | | | | | | | ~ | | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | Hand Brake | | | |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | | .0 | mm |
| | | | | | | Right front | 2 | .0 | mm |
| r | | | | | | Left rear | 4 | .0 | mm |
| Conditions During Body Inspection: Dry | | | | | | 3 1.0 | | | mm |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes | | | |
| | mage & Under bor | inet inspectic | on comments | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | GOOD | | | | | Head lights | ~ | | |
| Correcto | GOOD | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | GOOD | | | | | Dashboard warning lights | ~ | | |
| | , GOOD | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General Comments | | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | I | 1 |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | | | |
| Road Conditions During Test Drive: Dry | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Cambelt | | | | | | Sat. Nav. (basic test only) | - | | ~ |
| Evidence of Cam Belt Replacement: No Kms: | | | | | | Reversing camera | | | ~ |
| | | | | | | | | | |
| Inspected by: JAMES Date: 07 Aug 2018 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: