

Basic Vehicle Condition Guide

Report ID: 18,302,184


Version: 2

Created: 31 Jul 2018

Make: Model: MGF **Body Style:** Sports Car Rover Year: 1,996 Registration: DUL336 Reg Expiry: 14 Oct 2018 **WoF Expiry: Odometer:** 28 Oct 2018 **Good No:** 18302184 85,861 Kms VIN: SARRDWBGBAD00323 Next Service: **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Wear and tear on soft top

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil leak from engine and transmission Underbody surface rust Brake booster rusty

| | Interior Comments | | | | | |
|--|-------------------|---------|--|--|--|--|
| | Seats | Average | | | | |
| | Carpets | Average | | | | |
| | Panels | Average | | | | |
| | Dashboard | Average | | | | |

General Comments

AC less cooling

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt
Evidence of Cam Belt Replacement: No.

No

Kms:

| Inspected by: | Mathew Varghese | Date: | 31 Jul 2 | 2018 |
|---------------|-----------------|-------|----------|------|
|---------------|-----------------|-------|----------|------|

Name:

| | Pass | Fail | N/A | | | | | |
|--------------------------------|---------------------------------------|---------|----------|--|--|--|--|--|
| Engine | | | | | | | | |
| Oil level | ~ | | | | | | | |
| Smoke & fumes | ~ | | | | | | | |
| Performance | V V | | | | | | | |
| Noise | ~ | | | | | | | |
| Cooling System | | | | | | | | |
| Coolant condition | ~ | | | | | | | |
| Performance | ~ | | | | | | | |
| Radiator / Hoses (visual) | ~ | | | | | | | |
| Transmission | | | | | | | | |
| Operation | ~ | | | | | | | |
| Noise | ~ | | | | | | | |
| Clutch | ~ | | | | | | | |
| CV joints | \(\times \) | | | | | | | |
| Wheel bearings | ~ | | | | | | | |
| Brakes | | | <u> </u> | | | | | |
| Performance | ~ | | | | | | | |
| Hand Brake | ~ | | | | | | | |
| Tyres (lowest observed tread | l denth | of tyre | es) | | | | | |
| Left front | · · | 5 | mm | | | | | |
| Right front | | 5 5 | mm | | | | | |
| Left rear | | 3 | mm | | | | | |
| | | | | | | | | |
| Right rear 4 mn | | | | | | | | |
| Spare Yes Suspension | | | | | | | | |
| Suspension performance | ~ | | | | | | | |
| Steering performance | ~ | | | | | | | |
| Shock absorbers | ~ | | | | | | | |
| Air Conditioning / Heater | | | | | | | | |
| Operation | ~ | | | | | | | |
| Electrical / Accessories | | | | | | | | |
| Head lights | V | | | | | | | |
| Tail lights | <i>y</i> | | | | | | | |
| Indicators | <i>y</i> | | | | | | | |
| Dashboard warning lights | 1/ | | | | | | | |
| Wipers (front & rear) | > > > > > > > > > > > > > > > > > > > | | | | | | | |
| Window winder FL | 1 | | | | | | | |
| Window winder FR | • | | | | | | | |
| Window winder RL | | | ., | | | | | |
| Window winder RR | | | ., | | | | | |
| Rear view mirrors | | | - | | | | | |
| | | | | | | | | |
| Radio (basic test only) | | | ., | | | | | |
| CD (basic test only) | _ | | | | | | | |
| Number of leave | 2 | | | | | | | |
| Number of keys | - , | | 1 | | | | | |
| Central locking | <i>V</i> | | | | | | | |
| Central locking Remote locking | <i>v</i> | | | | | | | |
| Central locking | <i>V</i> | | V | | | | | |

Signature: