

Report ID: 18,303,064 Version: 2 Created: 03 Oct 2018

Make:	Nissan	Model:	Leaf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	Registration:	lke515	Reg Expiry:		Engine	I	L	L
WoF Expiry:	11 Apr 2019	Odometer:	78,058 Kms	Good No:	18303064	Oil level			~
VIN:	7AT0DH8KX18054613	Next Service:	-,	Service Histor		Smoke & fumes			~
						Performance			~
	port is not a warranty	oration is made	for and milaana	Darts have not	been dismonthed or	Noise			~
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechar	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	-		~
Key:		-0		-161-		Radiator / Hoses (visual)			~
S = scratch						Transmission			-
D = dent	- HE			TIN		Operation	~		
R = rust PT = paint def				\int		Noise	~		
C = crack						Clutch	•		~
P = pin dent						CV joints	~		
* = decals	616			- NL	ELIP-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	e defects & blemishes	may not be disr	blaved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftvre	<u> </u>
Hatch weather seal damage						Left front 5 mm			
						Right front			 mm
						Left rear	4		mm
							3		-
Conditions During Body Inspection: Wet						Right rear 4 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare N/A			
	inage a onder bor	<u>ince inspectie</u>	connents			Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		<u> </u>
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		<u> </u>
	-					Window winder FL	~		<u> </u>
Ganaral	-ommonts					Window winder FR	~		<u> </u>
<u>General Comments</u>						Window winder RL	~		<u> </u>
						Window winder RR	~		ļ
						Rear view mirrors	~		ļ
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		. <u> </u>
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Jason Law Date: 03 Oct 2018									

I have read and understood this condition guide.

Name:

Signature: