

Report ID: 18,303,283 Version: 1 Created: 31 Jul 2018

Make:	Nissan	Model:	Fuga	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,008	Registration:		Reg Expiry:		Engine	I		1
WoF Expiry:		Odometer:	79,596 Kms	Good No:	18303283	Oil level	~		
VIN:	7AT0DH8GX18300964	Next Service:	89500	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and miloago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust				715	HIL	Operation	~		
PT = paint defe				$\left[\right] \left[\right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	-110				74114	CV joints			~
* = decals	616			The		Wheel bearings	~		
SC = stone chips						Brakes			<u>. </u>
W = significan	t scuffs					Performance	~		
		Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	· ·		
Body Insp	pection Comments			, ,	, ,	Tyres (lowest observed tread	•	of tyre	Ls)
									mm
						Right front	6		mm
						Left rear			mm
Conditions During Rody Inspection.						Right rear	-	•	
Conditions During Body Inspection: Dry						Spare	0		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		I
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I					Window winder FR	~		
General Comments					Window winder RL	~			
	_					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys			L
Bood Conditions During Test Drives						Central locking	1		
Road Conditions During Test Drive: Wet						Remote locking	~		
Engine Tir	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	•		
Evidence of Cam Belt Replacement: Not Applicable Kms:									~
						Reversing camera	~		<u> </u>
Inspected by: Bobby Zhong Date: 31 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: