

Report ID: 18,303,347 Version: 1 Created: 23 Aug 2018

Make:	Toyota	Model:	Spacio	Body Style:	Wagon		Pass	Fail	N/A
Year:	1,998	<b>Registration:</b>	CSD425	Reg Expiry:	17 Sep 2018	Engine	1		L
WoF Expiry:	29 Nov 2018	Odometer:	140,057 Kms	Good No:	18303347	Oil level	~		
VIN:	7A8H6350705067346	Next Service:	141000	Service History	<b>y:</b> No	Smoke & fumes	~		
						Performance	r		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	sc	-0	S SC S		s	Radiator / Hoses (visual)	V		
S = scratch						Transmission			<u> </u>
D = dent R = rust SC W A A A A A A A A A A A A A A A A A A						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals SC 99						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W W S W SC						Performance 🖌			
						Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
Stonechip windowscreen						Left front		.6	mm
						Right front		.0	mm
						Left rear	2		mm
Conditio	s During Body Ins	pection:				Right rear		.9	mm
Conditions During Body Inspection: Dry						Spare	5 510		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
No under body inspection						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			<u> </u>
						Operation	~		
Interior Comments						Electrical / Accessories			<u> </u>
Seats	Good					Head lights	~		
	Coord					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		<u> </u>
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	•		~
						Number of keys	4		-
Pood Conditions During Test Driver						Central locking	4		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
	•		-						
Inspected by: Jamie Cook Date: 23 Aug 2018									
I have read and understood this condition guide. Name:									