

Report ID: 18,303,427 Version: 1 Created: 07 Sep 2018

Make:	Daihatsu	Model:	Terios	Body Style:	Wagon		Pass	Fail	N/A
Year:	1,998	<b>Registration:</b>	WW9021	Reg Expiry:	30 Sep 2018	Engine	1		
WoF Expiry:	09 Nov 2018	Odometer:	213,029 Kms	Good No:	18303427	Oil level	~		
VIN:	JDAJ100G000517487	Next Service:	216837	Service History	V: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	S SC	-0	S P SC S P SC		S P SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission	<u>, , , , , , , , , , , , , , , , , , , </u>		
D = dent R = rust PT = paint defect						Operation	~		
						Noise	~		
PT = paint defect C = crack						Clutch	~		
P = pin dent						CV joints	~		
* = decals SPTPSC Q Q						Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs S SC S D SC S P SC S P SC						Performance	~		
		Note: con				Hand Brake			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								~ <b>f t</b>	
Minor stone chips in the windscreen ,indicator broken in front bumper ,						Tyres (lowest observed tread			
						Left front		5 mm	
						Right front		1	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear		7	mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	mage & onder bor	metmspectic	<u>In comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Interior Comments drivers seat ripped, wear and tear,						Electrical / Accessories			
Seats	unvers sea	at rippeu,wear ar	iu tear,			Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Daabbaa	Average					Wipers (front & rear)	~		
Dashboa	ra -					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	V		
						CD (basic test only)	V		
						Number of keys	2		1
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
							1		
Inspected by: Donovan Matara Date: 07 Sep 2018									
I have read and understood this condition guide. Name:									