

Report ID: 18,304,285 Version: 3 Created: 02 Aug 2018

Make:	BMW	Model:	5 Series	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,008	Registration:	HHC294	<b>Reg Expiry:</b>	24 Nov 2018	Engine			
WoF Expiry:	12 Mar 2019	Odometer:	113,891 Kms	Good No:	18304285	Oil level	~		
VIN:	WBANU52060CZ8726	Next Service:	120000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for any and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0				Radiator / Hoses (visu	al) 🖌		
S = scratch						Transmission			
D = dent R = rust SC						Operation 🖌			
PT = paint defe				$\left[ \right] \left[ \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				거네	CV joints	~		
* = decals	sc 919			The	<b>HIP</b>	Wheel bearings	· ·		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Dealerteen	<u></u>	Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	· ·		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
								mm	
						Right front	-	3.0	mm
						Left rear		).0	mm
Conditions During Body Inspection: Dry						Right rear		0.0 mm	
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor oil leak at engine						Suspension performa	nce 🖌		
Sway links l	knocking worn					Steering performance			
						Shock absorbers	· ·		
						Air Conditioning / Hea			
						Operation	<b>v</b>		
Interior Comments						Electrical / Accessories			
Seats Good						Head lights	· ·		
						Tail lights	· ·		
Carpets	Good					Indicators			
Panels	Good					Dashboard warning li			
						Wipers (front & rear)			
Dashboa	rd Good					Window winder FL			
						Window winder FR			
General C	<u>Comments</u>					Window winder RL			
						Window winder RR			
						Rear view mirrors	· ·		
						Radio (basic test only)			
						CD (basic test only)	· ·		
						Number of keys	2	1	L
Road Conditions During Test Drive: Dry						Central locking	Z		
			Dry			Remote locking			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test or			
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	··;) •		~
	•	•							•
Inspected by: Dion Mair Date: 31 Jul 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....