

Report ID: 18,304,762 Version: 2 31 Jul 2018 Created:

Make:	Mazda	Model:	Mazda3	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,014	Registration:	HLW179	Reg Expiry:	16 Sep 2018	Engine	1		L
WoF Expiry:	,	Odometer:	47,947 Kms	Good No:	18304762	Oil level	~		
VIN:	JM0BM547810128362	Next Service:	54371	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
	W				D	Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust	w AR			210	HIVW	Operation	~		
PT = paint defe	ect NP				101h	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	sc de				74116	CV joints	~		
* = decals				10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	P SC					Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Right inner sill needs painting						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front	6.0 mn		mm
						Right front	6.	.0	mm
						Left rear	6.	.0	mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Steering performance							~		
Shock absor							~		
						Air Conditioning / Heater	er		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dashboa	iu l					Window winder FL	~		
						Window winder FR	۲		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanicm						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Brian Hill Date: 31 Jul 2018									
Date: 51 Jul 2016									

I have read and understood this condition guide.

Name:

Signature: