

Report ID: 18,304,903 Version: 1 Created: 12 Aug 2018

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2,013	Registration:	GZR328	Reg Expiry:	28 Oct 2018	Engine			
WoF Expiry:	01 Sep 2018	Odometer:	203,521 Kms	Good No:	18304903	Oil level	~		
VIN:	MR0FZ22GX01075015	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty	untina in mondo	for one and miles as	Danta hava nat	hoon dismonthed or	Noise	~		
diagnostic te	a guide only. Conside sting undertaken. The	ehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System	-		
a full mechan	nical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	sc	-0	ls		S SC	Radiator / Hoses (visual)	~		
S = scratch	STE	A U			XXX	Transmission	•		
D = dent	S D SC			The	EID SD	Operation	~		
R = rust				10	THIA	Noise	~		
PT = paint def C = crack				+	SC	Clutch	•		~
P = pin dent	Ho					CV joints	~		
* = decals	sc pip			AL-	ENR	Wheel bearings	-		
SC = stone chips						Brakes	~		
W = significant scuffs						Performance			
		Notorcom		may not be disr	laved in the diagram	Hand Brake	~		──
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	- <b>f h</b> m	
Stone chip on front windshield FR park light not working						Tyres (lowest observed tread depth of tyres)			
rh park ligi	It not working					Left front	7		mm
						Right front	7		mm
						Left rear	6		mm
Conditions During Body Inspection: Dry					Right rear	6 mm			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	inet inspectic	<u>In comments</u>			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		<u> </u>
carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dashboa	iiu					Window winder FL	~		
	_					Window winder FR	~		
<u>General</u> (	<u>Comments</u>					Window winder RL	<		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		
Road Con	ditions During Test	: Drive:	Dry			Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
						L			
Inspected by: Mathew Varghese						Date: 12 Aug 20	18		
I have read	and understood th	is condition a	uide. Name: .			Signature:			