

Report ID: 18,305,613 Version: 3 Created: 28 Sep 2018

Make:	Honda	Model:	Odyssey	Body Style:	People Mover		Pass	Fail	N/A	
Year:	2015	<b>Registration:</b>	HYU475	<b>Reg Expiry:</b>	11 Mar 2019	Engine			•	
WoF Expiry:	05 Apr 2019	Odometer:	114,683 Kms	Good No:	18305613	Oil level	~			
VIN:	JHMRC1850FC200022	Next Service:	119000	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and tr	lis can be arranged to	or an additional C	narge.	Coolant condition	~			
	S		S P P			Performance	~			
Key:		=		5(0)-		Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
R = rust	SD PR			10		Operation	~			
PT = paint defe	ect NP					Noise	~			
C = crack					SC	Clutch			~	
P = pin dent	HIP				74II <u>L</u>	CV joints	~			
* = decals SC = stone chips						Wheel bearings	~			
W = significant scuffs						Brakes				
in significant	W	$\mathbf{C}$	P P	W		Performance	~			
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Stonechip on windscreen						Tyres (lowest observed tread depth of tyres)				
						Left front	3	3	mm	
						Right front	3	3	mm	
						Left rear		3	mm	
Conditions During Body Inspection: Wet						Right rear	3 mm		mm	
						Spare	N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
Carpote	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Average					Dashboard warning lights	~			
Dashboa	rd Good					Wipers (front & rear)	~			
	iu					Window winder FL	~			
						Window winder FR	~			
General Comments						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Wet						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~			
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected by: Ca Thach Date: 28 Sep 2018										

I have read and understood this condition guide.

Name: .....