

## **Basic Vehicle Condition Guide**

Report ID: 18,305,700


Version:

Created: 31 Jul 2018

Make: Model: Mitsubishi L300 **Body Style:** Van Year: Registration: DCH639 Reg Expiry: 07 Feb 2019 2,006 WoF Expiry: **Odometer:** 30 Jan 2019 **Good No:** 18305700 159,393 Kms VIN: JMAHNP15V6A800292 **Next Service: Service History:** unknown No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Small cracks in tail lights. R /F park light cracked & loose. Roof gutters bent.

L/H wing mirror cracked.

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

OK.

Interior Comments			
Seats	hole in drivers seat .		
Carpets	hole on drivers side .		
Panels	Average		
Dashboard	Average		

## **General Comments**

Good size work van. C/D not working, radio ok.

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

**Daryll Timms** 

**Evidence of Cam Belt Replacement:** No Kms:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\( \triangle \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			1
Operation	~		
Noise	~		
Clutch	~		
CV joints			~
Wheel bearings	~		
Brakes	1	1	-
Performance	V		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	2 mm		
Right front	4		mm
Left rear	6		mm
Right rear	6		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			1
Operation			~
Electrical / Accessories			I
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	v v		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	<u> </u>		~
Window winder RR			~
Rear view mirrors			~
Radio (basic test only)	V		<u> </u>
CD (basic test only)		~	
Number of keys	1		I
Central locking	·		
Remote locking	<del>-</del>		~
Sat. Nav. (basic test only)			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Satiration (Dasic (Est Offis)	1	1	"

I have read and understood this condition guide.

Name: .....

Signature: .....

31 Jul 2018

Reversing camera