

Report ID: 18,305,825 Version: 1 Created: 03 Aug 2018

Make:	Hyundai	Model:	120	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,016	Registration:	JUS870	Reg Expiry:	26 Aug 2018	Engine			L
WoF Expiry:		Odometer:	70,277 Kms	Good No:	18305825	Oil level	~		
VIN:	MALBB51CMGM7069;	Next Service:	83000	Service History		Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust	sc			210		Operation	~		
PT = paint defe	ect NP				10111	Noise	~		
C = crack						Clutch			~
P = pin dent	sc de				24114	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w – signincan	W		S			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
					Left front 4			mm	
						Right front	4 mm		mm
						Left rear	6	5	mm
Conditions During Body Inspection: Wet						Right rear	6 mm		mm
						Spare	pare Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Clean						Suspension performance	~		
Steering performance							~		
Shock absorbers							~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	<		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
						Central locking	~		
Engine Ti	ning Machaniana		- ·			Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Stuart Melbourne Date: 03 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: